

Oil Field Environmental Incident Summary

Incident: 20150901182814

Date/Time of Notice: 09/01/2015 18:28

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 9/1/2015

Time Incident: 16:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 96

Sec: 3

Qtr: NW NE

Location Description: Spill occurred offsite 150 yards SE from the Teton 21-3H well, which is located at 03 -Township 150 N Range 96 West.

Submitted By: Curtis Blaik

Received By:

Contact Person: Curtis Blaik

PO BOX 51810

MIDLAND, TX 79710-1810

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 450 Feet

Distance Nearest Water Well: 1000 Feet

Type of Incident Pipeline Leak

Release Contained in Dike No

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

8

Barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risk to human health or the environment.

Areal Extent:

Potential Environmental Impacts:

No immediate environmental impacts from the spill.

Action Taken or Planned:

Landowner will be notified and the spill cleaned up by excavating contaminated soil.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 9/2/2015 **Status:** Reviewed; Followup Required **Author:** Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Pipeline leak impacted surrounding area. Followup required.

Date: 9/2/2015 **Status:** Post-inspection Update **Author:** Washek, Sandi

Updated Oil Volume:

Updated Salt Water Volume: 8.00 barrels

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 9:30 a.m. Weather was sunny, 74 degrees. The area of impact is located in a field southwest of the pad. GPS N47.84580, W102.95782
You can see visible product on the surface of the soil. Area is about 30 feet by 10 feet on the surface of the stubble field.

Cleanup company is Steiner Oilfield Services; Conoco Philips will be overseeing the cleanup. Soil will be removed, the pipeline inspected and clean soil used to fill in the area impacted. Soil samples will be collected and sent for analysis. Sample results will be provided to NDDoH. Landowner stopped by and talked to NDDoH inspector and company personnel on site. He expressed concern about the issue and the need to have the area properly cleaned up. Additional followup will be needed for this site.